



Bulletin Number: 09262024
Date: October 1, 2024
Subject: Teflon Removal on Dual Disc Valves

In an effort to eliminate PFAS from our products we will be updating the inlet and outlet discs removing the Teflon surface on all of our dual disc valves. This change impacts all products using the dual disc valve as well as the service part kits which are designed to be backwards compatible with systems already in the field.



Old (Left) New (Right)

To ensure a smooth transition to the new part without Teflon we have updated the part numbers of our service part kits.

The new service part kits are as follows:

New PN	New Description
7400154	KIT DISC EWS FILTER W/O TEFLON
7400170	REPL DISC KIT EWS W/O TEFLON
7400188	INLET DISC 7399094 10PK
7400196	OUTLET DISC 7399109 10PK

New PN	New Description
7399094	ROTOR ASM INLET W/O TEFLON
7399109	ROTOR ASM OUTLET W/O TEFLON
7400120	OUTLET DISC ASM, MACH. W/O TEFLON

Thank you,

EcoWater Systems

EcoWater Systems LLC | 1890 Woodlane Drive, Woodbury, MN 55125

EcoWater | 1890 Woodlane Dr | Woodbury, MN 55125 US

[Unsubscribe](#) | [Update Profile](#) | [Constant Contact Data Notice](#)



Try email marketing for free today!