## **Product Bulletin**

**Bulletin No.:** 07152024


Date: <u>July 15, 2024</u>

Subject: ERO385E and HERO385PLUS Production Resumes



Thank you for your patience as we made the required tooling modifications to comply with the new coin cell battery legislation, Reese's Law. We are excited to be back in production and will have the ERO385E and HERO385PLUS in addition to the replacement manifolds available to order on Friday the 19<sup>th</sup> with shipments beginning on Monday the 22<sup>nd</sup>.

The primary change is that the manifold cover now has two screws installed at the factory that are used to secure it to the manifold to prevent accidental access. These screws also have a retainer to hold them in the cover prior to installation. Due to common parts, this change applies to the standard ERO385 and ERO175 providing a more secure cover there as well.



System	Part Number	Status	
HERO385PLUS	7382607	Available to Order July 19 <sup>th</sup> , Shipping Resumes July	
		22nd	
ERO385E	7382592	Available to Order July 19 <sup>th</sup> , Shipping Resumes July	
		22nd	
ERO385	7382584	NOT IMPACTED. IN FULL PRODUCTION	

Service Part	Part Number	Status
Replacement Manifold Kit 385, Electric	7384374	Available to Order July 19 <sup>th</sup> , Shipping
		Resumes July 22nd
Manifold 375	7285376	Available to Order July 19 <sup>th</sup> , Shipping
		Resumes July 22nd

Thank You.

**Product Management**